WELL REPORT AATER STATE OF WASHINGTON

Start Card No. Water Right Permit No

-----FREELAND, WA 98249-Address P.O. BOX 652 (1) OWNER: Name QUADE, ROLLAND & MARY - SW 1/4 SE 1/4 Sec 28 T 29 N., R 3E WM (2) LOCATION OF WELL: County ISLAND
- SW 1/4 SE 1/4 Sec 28 T 29 M., R 3E WM
(2a) STREET ADDRESS OF WELL (or nearest address) 6717 S HAXWELTON RD (10) WELL LOG (3) PROPOSED USE: DOMESTIC Formation: Describe by color, character, size of material Owner's Number of well (4) TYPE OF WORK: and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with (If more than one) Nethod: ROTARY **NEW WELL** at least one entry for each change in formation. Diameter of well 6 inches (5) DIMENSIONS: FROM Depth of completed well 138 ft. MATERIAL Drilled 139 BROWN SAND BROWN SAND & GRAVEL BROWN SILTY SAND BROWN SILTY SAND CLAY & GRAVEL BROWN SILTY SAND & CLAY 30 (6) CONSTRUCTION DETAILS: 54 56 102 ft. to 134 ft. to ft. to Dia. from +2 Casing installed: 54 56 Dia. from WELDED 102 GRAY SILTY SAND CLAY & GRAVEL 106 GRAY SILTY SAND Perforations: NO 110 117 BROWN SAND & GRAVEL BROWN SAND & MATER Type of perforator used SIZE of perforations 123 130 130 in. in. by 123 123 130 BROWN SILTY SAND CLAY & WATER ft. to ft. perforations from perforations from ft. to BROWN SAND & WATER perforations from ft. to Screens: YES HOUSTON Manufacturer's Name Hodel No. Type STAINLESS STEEL ft. to 138 ft. to slot size 18 from 134 Diam. 6 from slot size Diam. Size of gravel of t. Gravel packed: NO Gravel placed from ft. to To what depth? 18 Surface seal: YES Material used in seal PUDDELING CLAY Did any strata contain unusable water? NO Depth of strata Type of water? Method of sealing strata off (7) PUMP: Manufacturer's Name Land-surface elevation (8) WATER LEVELS: above mean sea level .. 99.5 ft. below top of well Date 10/17/90 lbs. per square inch Date Static level Artesian Pressure Artesian water controlled by Completed 10/17/90 Hork started 10/17/90 WELL CONSTRUCTOR CERTIFICATION: (9) WELL TESTS: Drawdown is amount water level is lowered below I constructed and/or accept responsibility for construction of this well, and its compliance with all static level. If yes, by whom? Was a pump test made? NO Washington well construction standards. Materials used hrs. gal./min with ft. drawdown after and the information reported above are true to my best knowledge and belief. Recovery data NAME HAYES DRILLING, INC. (Person, firm, or corporation) (Type or print) Water Level Time Water Level Time Water Level Time ADDRESS 556 ERSHIG RD. BOW, WA [SIGNED] Stave Filled License No. 762 Date of test / /
Bailer test 15 gal/min. 0 ft. drawdown after 1
Air test 35 gal/min. w/ stem set at 134 ft. for .5 hrs. Air test 35 Artesian flow hrs. Contractor's Date g.p.∎. Date 10/19/90 Registration No. HAYESD1106J5 Temperature of water Was a chemical analysis made? NO

RECEIVED

OCT 24 1990

DEPT. OF ECOLOGY